


NB2002X4 - BREAKDOWN



NB2002X4 - PARTS LIST

KEY NO	PART NO	DESCRIPTION	KEY NO	PART NO	DESCRIPTION
1	NM-88005	Hex. Soc. HD. Bolt	39	NM-10460	Stepped Pin
2	NM-10420	Deflector	40	NM-93001	Spring Pin
3	NM-99032	Hex. Soc. HD. Bolt	41	NM-10440	Primary Trigger
4	*	Seal	42	NM-10011	Secondary Trigger
5	NM-97002	Spring Washer	43	NM-99005	Hex. Soc. HD. Bolt
6	NM-28080	Cap	44	NM-94001	Air Plug
7	*	Seal	45	NM-28100	End Cap
8	*	O-ring	46	NM-96039	O-ring
9	*	Cap Gasket	47	NM-28010	Gun Body
10	*	Spring	48	NM-10640	Latch
11	NM-28090	HD. Valve Piston	49	NM-99003	Hex. Soc. HD. Bolt
12	*	O-ring	50	NM-97001	Spring Washer
13	*	Collar	51	NM-10019	Spring
14	NM-28190	C-ring	52	✓	Seal
15	+	O-ring	53	NM-10590	Latch Bracket
16	+	Piston O-ring	54	NM-10660	Pin
17	+	Piston Ram Assy.	55	NM-92001	Lock Nut
18	#	O-ring	56	NM-10630	Bracket
19	NM-28030	Cylinder Spacer	57	NM-10013	Trigger Valve Head
20	#	O-ring	59	NM-28140	Bracket
21	#	O-ring	60	NM-28120	Magazine Cover
22	NM-28020	Cylinder	61	NM-99002	Hex. Soc. HD. Bolt
23	# +	Bumper	62	NM-10490	Trigger Valve Assy.
24	NM-93009	Spring Pin	63	NM-28160	Latch Plate
25	NM-28340	Nose Cover Latch	64	NM-28170	Pusher
26	NM-28130	Nose Cover A	65	NM-10021	Shaft
27	NM-99004	Hex. Soc. HD. Bolt	66	NM-28360	Spring
28	NM-99006	Hex. Soc. HD. Bolt	67	NM-10020	Steel Plate
29	NM-97002	Spring Washer	68	✓	Spring
30	NM-28150	Safety	69	NM-10015	Trigger Valve Guide
31	NM-95002	E-ring	70	✓	O-ring
32	NM-10012	Spring	71	✓	O-ring
33	NM-10470	Rod			
34	#	Ram Guide			
35	NM-95001	E-ring			
36	NM-16540	Nose Cover B			
37	NM-28040	Nose			
38	NM-28110	Magazine			


See next page for Repair Kit contents

NB2002X4 - REPAIR KITS


* Key numbers 4, 7, 8, 9, 10, 12, and 13 can only be purchased as part of K-0517 Top Repair Kit.



+ Key numbers 15, 16, 17, and 23 can only be purchased as part of K-1850 Driver Blade Repair Kit.



Key numbers 18, 20, 21, 23, and 34 can only be purchased as part of K-0518 Bottom Repair Kit.



✓ Key numbers 52, 68, 70, and 71 can only be purchased as part of K-0519 Trigger Repair Kit.

